Hot Adhesives and Over-laminates

Adhesive Films Hot by LION



Superbond Hot Dry Mount Tissue

Best for bonding paper to board. 12gm² + 50gm² + 12gm² = 74gm²

	•	_	-	-	
9141	Superbond DMT 650mm x 25m	70°C to 115	°C Working	temperature	
6767	Superbond DMT 650mm x 50m	"	"	"	
6768	Superbond DMT 1040mm x 25m	"	"	"	
6769	Superbond DMT 1040mm x 50m	"	"	"	
6770	Superbond DMT 1300mm x 50m	"	"	"	

PUB123

Adhesive

Adhesive Tissue Adhesive

Acid-free Hot Mount Film

Unique hot and transparent adhesive film 25µ.


10751 Acid-free Hot Mount film 1040 mm x 25m 77°C to 88°C Working temperature



Clear Hot Dry Mounting Film

The strongest hot adhesive film. Works well with DiBond, aluminium and canvas $25\mu+50\mu+25\mu=100\mu$


9583	DMF Clear 650mm x 25m	85°C to 99°C Working temperature			
905	DMF Clear 1040mm x 25m	"	"	"	
9584	DMF Clear 1300mm x 25m	"	"	"	



Adhesive Hot Mounting Boards from LION

Helpful for faster dry mounting


2690	1.25mm SpeedMount Dry-mount 1125mm x 815mm by <i>ColourMount</i>
	80°C to 90°C Working temperature
10523	1.40mm Dry-mount on board 1020 x 810mm by Kool Tack
	70°C to 80°C Working temperature
10524	2.5mm Dry-mount on board 1020 x 810mm by Kool Tack
	70°C to 80°C Working temperature
10525	5.0mm Dry mount on foam board 1020 x 810mm by Kool Tack
	70°C to 80°C Working temperature
SAMPO	9 Hot Board Samples Pack



Canvas Hot Adhesive Coated

Convenient when a customer wants canvas texture showing on a print.

6693 Adhesive Coated Canvas 1270mm x 10m roll 280gsm CLEARANCE 85°C to 99°C Working temperature



Over-Laminating Films Hot by LION

Over-laminating a poster or picture, hot or cold, can replace glass. This reduces damage risk in public places. The frame will also be much lighter. The designation 'pp' means that the over-laminating film is pre-pierced to help air and moisture to escape during the heat process.

GLOSS Clear Over-laminating film 75µ

PVC 50u + 25u = 75u

6812 Gloss clear film 1040mm x 25m pp 85°C to 99°C Working temperature

SATIN Clear Over-laminating film 75µ


 $PVC 50\mu + 25\mu = 75\mu$

9587	Satin clear film 650mm x 25m pp	85°C to 99°C Working temperature			
6816	Satin clear film 1040mm x 25m pp	"	"	"	
9588	Satin clear film 1300mm x 25m pp	"	"	"	

MATT Clear Over-laminating film 100µ

 $PVC 75\mu + 25\mu = 100\mu$

6820 Matt clear film 1040mm x 25m pp 85°C to 99°C Working temperature



Accessories for Hot Working

Release Paper, release coating on one side

9629 Silicone release paper, single sided 1240mm x 25m by LION

Release Paper, release coating on both sides

10737 Silicone release paper, double-sided 1240mm x 25m by LION

Release Film, clear, release coating on both sides

Users often find that clear double-sided release film facilitates alignment of the workpiece, and that it can last longer than release papers. It is less prone to creasing.

1906 Silicone release film double-sided 1070mm x 10m

7833 Silicone release film double-sided 1070mm x 25m

5828 Silicone release film double-sided 1300mm x 10m

Silicone release film double-sided 1300mm x 25m

Flat-Bed Press

Gas Heated

'Iron' press mounts photos 200 x 150mm / 8" x 6" in an album,

using shellac coated

tissue

Often around 600 x 600mm / 24" x 24" Ideal for photos. Can step and repeat for larger prints.



Accessories For Hot and/or Cold Working

10754 Heavy Duty Snap-Off Knife 18mm KC1

37 Snap Off Blades 18mm pack 10

10755 Heavy Duty Utility Blade Knife

10756 Folding Utility Blade Knife

507 Stanley 50mm type #1991 Blades pack 100

508 Stanley 60mm type #1992 Blades pack 100

2907 Cutting mat A4 300 x 230mm 3mm

2908 Cutting mat A3 450 x 300mm 3mm

6343 Cutting mat A2 600 x 450mm 3mm

10636 Cutting mat 1200 x 900mm 3mm Rhino

10635 Cutting mat 1800 x 900mm 3mm Rhino

4701 StaticWisk Anti-static brush 140mm

Tacking Iron 240v Polished flat smooth tip

Foam blanket 5mm 2000 x 1150mm, best for HGP vacuum presses

922 Foam blanket 13mm 2000 x 1150mm, best on HGP to press the

laminating film into the surface texture of the canvas

Mechanical Press

Typically 580 x 470mm / 22" x 18 and 860 x 660mm /33" x 25"



Hot Press HGP

Vacuum presses, HGP260 1194 x 890mm / 47" x 35" and HGP360 1689 x 1080 / 66" x 42"



Step-and-repeat with a flat-bed press

This procedure can allow work on items more than 24"x24" / 605 x 605mm. A **release board** which helps slide the large workpiece into the press. This is a sheet of MDF with a sheet of single-sided release paper dry-mounted to the smoothest side.

The square, edges of the heated platen can leave edge marks on over-size workpieces. To minimise that, source a sheet of flat and **smooth aluminium sheet** about 4"/100mm larger all round. Thickness should be 20g as a minimum and up to 4mm, depending on the budget. This sheet is placed over the workpiece and centrally under the heated platen.

Dust Cover Cloths for Presses

For all cold or hot mounting, a dust free-free work area will help ensure quality work. Almost any dust-proof fabric will do. If it's for a hot press, only place it over the machine when it is switched off and cooled down. A tip for users of Hot Press HGP machines - leave it with the top down, but not latched tight.



Technical Support & Training in Hot and Cold Mounting by LION

If you have a press the same or similar to any of those shown, the LION Tech Team will try to help you resolve any issues which may be prevent it being used. By appointment, they can also do refresher training. Email: techserve@lionpic.co.uk

The book 'The Mounting & Laminating Handbook' by Chris Paschke CPF GCF, is truly the bible for all kinds of mounting; hot, cold and conservation. Just a couple of extra jobs will cover its cost. 3771

To see the LION
Cold materials range
read PUB122.
Go to 6977 and click
on Downloads



v.1 A09